# Interagency Site Transfer Form For UST inspections at new Trust Land Properties Between US EPA and WA State Dept. of Ecology July 14, 2014

This is a checklist to standardize site jurisdiction transfers for Trust Lands owned by Native American Indian Nations from the State to Federal. This agreement is only for the specific purposes of transferring regulated Underground Storage Tanks as described in RCW 90.76 and WAC 173-360, and is limited to sites that are not contaminated as described in MTCA 70.105D RCW, Uniform Environmental Covenants Act Chapter 64.70 RCW, and MTCA Cleanup Regulations 173-360 WAC.

In Washington State, when properties are acquired by an Indian Nation and become Trust Land the regulatory authority for UST's becomes the US EPA. To better facilitate this transfer the following flow sheet has been developed.

- ✓ Notification EPA will make a request in writing to Ecology's Toxics Cleanup Program Manager (or appointed staff) to transfer jurisdiction for the UST site to US EPA as it has become trust land.
- ✓ Ecology's Program Manager (or appointed staff, UST/LUST Coordinator) will approve the jurisdictional transfer from State to Federal, and notify the appropriate UST staff to perform the following actions:
  - a. Make a COPY of the UST file in the region and headquarters and furnish them to EPA
  - b. Notate in the Ecology files with a Notice of what date the jurisdictional transfer occurred and make the changes to the UST database to reflect these changes.

Agency transfer date: 4	9015	
UST Application updated	Γ	Date:
ISIS updated (If needed)	Г	Date:
Pdf copy sent to EPA	, T	Date:

# A COPY OF THE ENTIRE FILE WAS SENT TO EPA ON 10/1/97.

Alaska Idaho Oregoi. Washington central Kiges

DEPARTMENT OF ECOLOGY CENTRAL REGION OFFICE



Attn Of:

MAY 2 9 1992

WD-139

#### CERTIFIED MAIL - RETURN RECEIPT REQUESTED

Robert Reynolds, Trustee in Bankruptcy for R.H. Boyles Co., Inc. 901 Summit View, Suite 251 Yakima, Washington 98902

RE: Information Request

Docket No. 1092-05-12-9005

Dear Mr. Reynolds:

You are hereby served in your capacity as Trustee for R.H. Boyles Co., Inc., with an Information Request pursuant to Section 9005 of the Resource Conservation and Recovery Act (RCRA), as amended, 42 U.S.C. §6991d.

Section 9005 of RCRA authorizes the United States Environmental Protection Agency (EPA) to request from any owner or operator of an underground storage tank (UST) information relating to such tanks.

This Information Request requires that R.H. Boyles Co., Inc., provide timely and adequate answers to all of the questions set forth therein. EPA also requires that a representative of the R.H. Boyles Co., Inc., certify with the enclosed affidavit that the responses are true, accurate and complete. A response must be provided within 14 days of receipt of this Information Request.

If you have any questions regarding this matter, please call Todd Bender of the Regional Underground Storage Tank Program, at (206) 553-0344 for technical matters, or Deborah Hilsman of the Office of Regional Counsel, at (206) 553-1810 for legal matters.

Sincerely,

Charles E. Findley

Director, Water Division

Enclosures:

Information Request

Affidavit

40 C.F.R. Part 280

WDOE, Central Region, Yakima cc:

9

10

11

12

13

14 15

16

17

18

19

20

21 22

23 24

25

26

27

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY Region 10 1200 Sixth Avenue Seattle, Washington 98101

IN THE MATTER OF:	
R.H. Boyles Co., Inc.	) ) Decket No. 1000 05 10 0005
(BRAND X Facility in	Docket No. 1092-05-12-9005
Toppenish, WA)	
	) INFORMATION REQUEST
Respondent	

Pursuant to Section 9005 of the Resource Conservation and Recovery Act, as amended (RCRA), 42 U.S.C. Section 6991d, the Environmental Protection Agency (EPA), through the Director of the Water Division, and upon the basis of available information, hereby issues this Information Request:

#### BACKGROUND INFORMATION

- 1. Brand X Tank and Tummy (Brand X), owned by R.H. Boyles Co., Inc. (Respondent) and operated as a petroleum bulk storage and retail plant is located within the confines of the Yakima Reservation on the southwest corner of Fort Road and Elm Street, in Toppenish, Washington.
- Two or more underground storage tanks (USTs) are (or have been) located at this Brand X facility.
- 3. R. H. Boyles Co., Inc., is the owner of USTs as those 28 terms are defined under Sections 9001 and 9002 of RCRA.

- 4. Owners and operators of USTs located on Indian Lands were required to notify the EPA, as the implementing agency, of their existence if the UST systems were either in operation on or after May 8, 1986, or taken out of operation and managed in place subsequent to January 1, 1974.
- 5. EPA, Region 10, has not to date received notification for the USTs at this Brand X facility.
- 6. Owners and operators of USTs are required to provide a method or combination of methods of release detection for their USTs by the applicable date established in the schedule set forth in 40 C.F.R. Sections 280.40-45 (see enclosed schedule of compliance dates).
- 7. EPA, Region 10, has reason to suspect that petroleum releases have occurred from the USTs at this Brand X facility.
- 8. Owners and/or operators of petroleum or hazardous substance USTs which have created a release to the surface or subsurface environment must comply with the release response requirements set forth in 40 C.F.R. §280.50 §280.65.

#### INFORMATION REQUEST

For purposes of responding to this Information Request,
 the following definitions apply.

The term "underground storage tank" means any one or combination of tanks (including underground pipes connected thereto) which is used to contain an accumulation of regulated substances, and the volume of which (including the volume of the underground pipes connected thereto) is 10 percent or more beneath the surface of the ground.

The term "regulated substance" means (a) any substance defined in Section 101(14) of the Comprehensive

Environmental Response, Compensation, and Liability Act of 1980 (but not including any substance regulated as a hazardous waste under Subtitle C), and (b) petroleum, including crude oil or any fraction thereof which is liquid at standard conditions of temperature and pressure.

The term "owner" means in the case of an underground storage tank in use on the date of enactment of the Hazardous and Solid Waste Amendments of 1984, or brought into use after that date, any person who owns an underground storage tank used for the storage, use, or dispensing of regulated substances.

The term "operator" means any person in control of, or having responsibility for, the daily operation of the UST system.

The term "release" means any spilling, leaking,
emitting, discharging, escaping, leaching or disposing from
an UST into ground water, surface water or subsurface soils.

- 10. Pursuant to the authority of Section 9005 of RCRA, 42 U.S.C. §6991d, Respondent shall, within fourteen (14) days of receipt of this Information Request, provide copies of any and all existing documents requested below, and/or complete and accurate responses to the questions set forth below.
  - (a) Provide the date of purchase by the current owner, and the names and addresses of the current and previous owners, of the facility. Provide the same information (dates and addresses) for current and previous

6

8

15

16

17

18 19

20

21

22

23 24

25

26

27

28

operators.

- Provide copies of any and all notification(s) submitted (b) to EPA, the implementing agency, of the existence of any and all underground storage tanks operated at this If notifications were submitted to the facility. Washington Department of Ecology in error, provide copies of such notifications.
- Indicate the number, size, age, type, location, uses, (C) and dates of use, of any and all USTs at this facility.
- Provide a description of the contents of each UST at (d) this facility. This description should, at a minimum, specify the type and quantity of product that was, or is now, stored in any and all USTs at this facility.
- Provide documentation of compliance with the release (e) detection requirements for tank(s) set forth at 40 C.F.R. §§ 280.41 and 280.43 for each UST Installed prior to 1975, or for which the date of installation is unknown, by providing either:
  - proof of purchase and installation of an automatic tank gauging system, vapor monitoring system, groundwater monitoring system or interstitial monitoring system; or
  - documentation of an annual tank tightness test and daily inventory records for January 1991 through the present, if the daily inventory control method of leak detection is used.
- Provide documentation of compliance with the release (f) detection requirements for piping set forth at 40

# C.F.R. §§ 280.41 and .44 by providing: FOR ALL PRESSURIZED PIPING:

- (1) Receipts for purchase and installation of an automatic line leak detector; and
- (2) Results from an annual line tightness test or results from a monthly monitoring program.

#### FOR ALL SUCTION PIPING:

Documentation of either

- (1) a line tightness test; or
- (2) use of monthly monitoring method conducted in accordance with § 280.44(c); or
- (3) evidence that the facility's suction piping meets the standards outlined in § 280.41(b)(2) (i through v), and, therefore, no release detection is required.
- (g) If, for any reason a release was suspected from any UST system at this facility, provide documentation of compliance with the release reporting, investigation and confirmation requirements set forth in 40 C.F.R. Part 280, Subpart E. Such documentation must include the results of a system test and a site check conducted in accordance with 40 C.F.R. § 280.52.
- (h) If the system test and/or site check indicated a release has occurred from the USTs at this facility, or if a release from the USTs has been identified in any other manner, then provide documentation of compliance with the release response and corrective action requirements set forth in 40 C.F.R. Part 280,

#### Subpart F. Such documentation must include:

- (1) A description of the initial response steps taken to prevent further release of regulated substances and to mitigate fire, explosion and vapor hazards pursuant to 40 C.F.R. §280.61, and the dates such steps were taken;
- (2) A copy of the report submitted to EPA summarizing the initial abatement steps taken as required by 40 C.F.R. §280.62. If no such report has been submitted, then provide a description of initial abatement measures conducted in response to the confirmed release pursuant to 40 C.F.R. §280.62;
- (3) Information concerning the initial site characterization including:
  - (a) Data on the nature and estimated quantity of release;
  - (b) Data on the use and approximate locations of wells potentially affected by the release;
  - (c) Description of subsurface soil conditions; and
  - (d) Locations of subsurface sewers.
- (4) Assessment of potential existence of free product phase contamination and plans for immediate removal of such contamination, including a detailed description of the remediation process;
  - 5) Assessment of volume and extent of

contaminated soils, including a detailed description of the remediation process; and

(6) A complete description of the hydrogeologic characteristics of the impacted area to all surrounding hydrogeologic divides.

- (i) Submit any and all information regarding any petroleum release at this facility, including, but not limited to any reports of discovery of release, and/or confirmation of release.
- (j) Provide copies of any and all information available regarding soil and/or ground water testing performed at this facility.
- (k) Indicate whether any petroleum contamination has been observed either in the soils or in/on the ground water at this facility.
- (1) Provide any and all documentation pertaining to the taking out of operation of any or all underground storage tanks or piping located at this facility, including, but not limited to: copies of any notification submitted to EPA, the implementing agency, or Washington State Department of Ecology of intent to permanently close the underground storage tanks or piping; copies of any records capable of demonstrating that a site assessment has been performed; and copies of any closure records filed.
- (m) Submit an outline of the procedures that were employed in permanently closing any and all existing tanks and piping pursuant to 40 C.F.R. § 280.71 through 280.74.

- 11. Failure to provide a timely response to this
  Information Request may subject Respondent to further action,
  including the filing of an administrative complaint which could
  result in liability of up to \$10,000 per tank for each day of
  continued noncompliance pursuant to Section 9006 of RCRA.
- 12. Respondent shall submit the information required in this Information Request to:

Director, Water Division
U.S. Environmental Protection Agency
1200 Sixth Avenue
Seattle, Washington 98101
Attn: Todd Bender, WD-139

- 13. Even if there is full compliance with this Information Request, Respondent shall not be relieved from liability to pay civil penalties or be subject to injunctive relief for any past or future violations of the Resource Conservation and Recovery Act, as amended, and its implementing regulations.
- 14. You are entitled to assert a claim of business confidentiality covering any part of the submitted information in the manner described in 40 C.F.R. Part 2, Subpart B. Information subject to a claim of business confidentiality will be made available to the public only in accordance with the procedures set forth in 40 C.F.R. Part 2, Subpart B. Unless a business confidentiality claim is asserted at the time the information is submitted, EPA may make such information available to the public without further notice to you.

15. Questions concerning this Information Request should be addressed to Todd Bender, of the Regional Underground Storage Tank Program, at (206) 553-0344 for technical matters, or Deborah Hilsman, Office of Regional Counsel, at (206) 553-1810 for legal matters. U.S. Environmental Protection Agency Charles E. Director, Water Division 

# 91287

DEPARTMENT OF ECOLOGY UNDERGROUND STORAGE TANKS

TEEL OF YAW

#### SITE ASSESSMENT REPORT FOR UNDERGROUND STORAGE TANK CLOSURE AT BRAND X TANK & TUMMY TOPPENISH, WA

For:

Gary Christensen
R. E. Powell Distributing, Inc.
501 East Main
Grandview, WA



By: David L. Green, R.S.A. Engineering Geologist

WHITE SHIELD, INC. P.O. Box 477 Grandview, WA 98930

May, 1991



## WHITE SHIELD, INC.

P.O. BOX 477 • GRANDVIEW, WA 98930 • (509) 882-1144 FAX (509) 882-4566



May 23, 1991

R. E. Powell Distributing, Inc. 501 East Main Grandview, WA 98930

Attention: Gary Christensen

SUBJECT: SITE ASSESSMENT REPORT FOR CLOSURE OF UNDERGROUND

STORAGE TANKS.

Dear Mr. Christensen,

Please find two copies of the exploratory investigation report as you requested. Based on the data and findings reported herein, we have determined that the groundwater is contaminated with gasoline at the southeast corner of the property. Although diesel was found in the groundwater across Elm Street, it is not likely to have originated from the same source as that found on the Brand-X property.

The Washington State Department of Ecology (DOE) requires that you retain this report for a minimum of ten years. We recommend you retain it indefinitely. The DOE also requires the property owner to report a spill of this nature within 24 hours. We have also provided a cost estimate for cleanup of the property. However, since the exact nature of the plume is unknown, this estimate is approximate.

We appreciate the opportunity to provide you technical assistance for your tank closure. Please call me at (509) 882-1144 should you have any questions or comments.

Respectfully Yours,

WHITE SHIELD, INC.

David L. Green, R.S.A. Engineering Geologist

Project Number: REP-0191

cc: lb

Pat Perrault

#### **Executive Summary**

White Shield, Inc. (WSI) provided exploratory investigation services at the Brand - X Tank & Tummy, Toppenish, WA. We tested the soil and groundwater for petroleum contamination following sample collection protocol as required by the <u>Guidance for Site Checks and Site Assessments for Underground Storage Tanks.</u> We completed our investigation on May 22, 1991. Based on our visual observations, analytical laboratory analyses, olfactory responses (smell), and interviews, we find petroleum contaminated soil and groundwater within the southeastern portion of the property. We also found petroleum contamination in the area of pit 1 that slightly exceeds cleanup guidelines.

The southeastern portion of the property contains the majority of petroleum contamination. We constructed two test pits on the opposite side of Elm Street and found that the groundwater is contaminated with diesel. It is unknown whether or not the diesel contamination originates from the assessed property. This can be ascertained during removal of lines and underground tanks at the Brand-X site. If it is determined that this contamination originates from the Brand-X property, extraction wells and a portable groundwater treatment unit is recommended for this area.

The soil and groundwater that is also contaminated in the southeastern portion of the property requires treatment. We estimate 2,500 to 3,000 cubic yards of soil must be removed from the area of pit 1 and pit 3. This should be treated by "landfarming". The contaminated groundwater must also be removed and treated utilizing air-stripping and/or activated carbon techniques. The extent of this treatment process will depend on many factors, but at this point, we estimate that a one-year air-stripping program will be necessary. Continuous monitoring of at least three monitoring wells will be required.

#### TABLE OF CONTENTS

1	0	IN	JTR	OD	IIC	TI (	M
			4 1 10	1/1/			<i>P</i>   V

- 1.1 Purpose
- 1.2 Scope of Work

#### 2.0 BACKGROUND INFORMATION

- 2.1 Site Location and Topography
- 2.2 Site Description and History
- 2.3 Regional Geology
- 2.4 Site Geology
- 2.5 Hydrology

#### 3.0 FIELD ACTIVITIES

- 3.1 General Investigative Methods
- 3.2 Exploratory Investigation

#### 4.0 INVESTIGATIVE METHODS AND RESULTS

- 4.1 Field Screening
- 4.2 Soil Sampling
- 4.3 Soil Chemistry
- 4.4 Groundwater Sampling
- 4.5 Groundwater Chemistry

#### 5.0 Recommendations

- 6.0 Conclusion
- 7.0 Limitations

#### LIST OF FIGURES

Figure 1. Regional Topography of the Toppenish Creek Basin. Figure 2. Street Map of Toppenish showing Site Location.

#### LIST OF APPENDICES

Appendix A: Field Form for Site Assessment of an Underground Storage Tank

Appendix B: Laboratory Report and Chain of Custody Documentation

Appendix C: Cleanup Guidelines from <u>Guidance for Site Checks and Site</u>
<u>Assessments for Underground Storage Tanks.</u>

#### 1.1 Purpose

This report describes findings and actions taken for work associated with the exploratory investigation at the Brand-X property. The purpose of our investigation involved determination of the presence or absence of petroleum contamination and a rough approximation of the extent groundwater contamination. The work and investigation responds to regulatory requirements set forth by the United States Environmental Protection Agency (EPA) and the State of Washington, Department of Ecology (DOE).

#### 1.2 Scope of Work

This report completes exploratory investigation services, provided by White Shield, Inc. (WSI), for determination of the presence or absence of significant petroleum contamination at the Brand-X in Toppenish, Washington. Upon discovery of contaminated groundwater, we expanded the scope of work to include an approximate determination as to the extent of contamination and cost for remediation of the affected area.


#### 2.0 Background Information

#### 2.1 Site Location and Topography

Toppenish is located within the southeast portion of the Toppenish Creek Basin (see Figure 1). The local topography dips very gently to the southeast following the Yakima River drainage. The Yakima River is approximately 2 miles northeast of the site and flows southeasterly to the Columbia River.

The Toppenish Creek Basin is bounded by Toppenish Ridge to the south, the Cascade Range to the west, and Ahtanum Ridge with Rattlesnake Ridge to the north. The topographic basin is divided by the Yakima River into two separate drainage areas.

The local topography slopes gently to the southeast, roughly paralleling the Yakima River.



The site is located in the southwest portion of the town (see Figure 2), on the southwest corner of Elm Street and Fort Road, Toppenish, WA. It is located within the NE 1/4, NE 1/4, NE 1/4, NE 1/4, Section 9, Township 10 North, Range 20 East, Willamette Meridian. The surrounding area consists of commercial businesses, of which three adjacent properties operate underground storage tanks.

#### 2.2 Site Description and History

The property operates as a bulk plant for distribution of petroleum products, a car wash and mini-mart which retails petroleum products. The western portion of the property consists of a bulk plant with five above ground storage tanks and fuel dispensers (truck rack). Immediately east of the above ground tanks are two abandoned underground tanks of unknown size. As indicated by the distance between fill spouts, the tanks are probably about 1,500 gallons each.

The western portion of the property is occupied by a small mini-mart with a car was attached to the southern portion of the building. Two 6,000 gallon tanks, containing regular and unleaded gasoline lie north of the building. Two 4,000 gallon tanks, containing regular and super unleaded gasoline lie east of the car wash. The retail dispensers are located north and east of the building. All tanks remain in place but are unused.

#### 2.3 Regional Geology

The ridges surrounding the Toppenish Creek Basin (discussed above) are composed of Columbia River Basalts and interbedded sediments of the Ellensburg Formation. The rocks of this region reflect a history of north-south compressional forces. These forces produced geologic structures (ridges and valleys) which affect surface and groundwater hydrology in areas adjacent to the river valley. An east-west trending anticline (ridge resulting from folding) lies approximately 18 miles north of the site. This anticline is structurally continuous, but has been geographically divided into Ahtanum Ridge and Rattlesnake Ridge. Union Gap separates these ridges. The foothills of the Cascade Range trend roughly north-south and lie approximately 25 miles west of the property. Toppenish Ridge trends roughly east-west and is located approximately 5 miles southwest of the property.




FIGURE 2 Steet Map of Toppenish

#### 2.4 Site Geology

The property is situated upon deposits consisting of Yakima River flood silts (clayey, sandy silt in the upper 4-5 feet). This flood silt was deposited during periods when the Yakima River flooded over the area.

Mainstream Yakima River gravels underlie the silt and extend to depths over 14 feet deep. These gravels were deposited when the Yakima river ran over the property. Over time, the Yakima River has meandered extensively over much of the eastern portion of the Toppenish Creek Basin.

The river deposit consists mainly of basaltic and andesitic cobbles and gravels up to 6 inches in diameter. The average size is approximately 2 inches in diameter. In the test pits we established (discussed below), there is no significant variance in particle size within the gravels.

#### 2.5 Hydrology

The major drainage features for this portion of the basin include Toppenish Ridge, the Cascade foothills, Ahtanum Ridge and the Yakima River. As mentioned in section 2.1, the land slopes very gently to the southeast paralleling the Yakima River. The nearest surface water, Wanity Slough, lies approximately 1/4 mile southwest of the site.

Groundwater is contained by an alluvial aquifer and deep basalt aquifers. The groundwater surface within the alluvial aquifer lies at a depth of about 13 feet at the site. We conducted a review of driller well logs registered with the WSDOE and records of City Wells held by the Toppenish Public Works Department. Our review finds that the general groundwater flow is toward the southeast. However, the exact direction of groundwater flow at the site is difficult to determine due to the lack of sufficient data. The nearest public water supply well is located approximately 1/5 mile from the site.

#### 3.0 Field Activities

#### 3.1 General Investigative Methods

We visually inspected the soil and groundwater by establishing test pits in areas most likely to be contaminated. We used field screening, analytical laboratory analyses, olfactory responses (smell), and interviews for data. The methods and general conclusions are discussed below.

#### 3.2 Exploratory Investigation

David L. Green, an engineering geologist registered with the Washington State Department of Ecology Underground Storage Tank Program, performed the investigation on May 6 and 23, 1991. The exploration began by establishing three test pits in areas most likely to exhibit contamination by petroleum products. These initial pits were established downgradient from Underground Storage Tanks and one of the dispenser islands. We sampled according to Guidelines for Site Checks and Site Assessments for Underground Storage Tanks (February, 1991). The attached Field Form for Site Assessment of Underground Storage Tanks (Field Form) provides a site map and other key data and is included as Appendix A. We detected petroleum odors and visual signs of contamination in pit 3 (see Field Form). We submitted 6 samples to Materials Testing and Consulting, Mt. Vernon, Washington for laboratory analysis and found that petroleum hydrocarbon concentrations are above action levels established by the WSDOE in pit 1 and pit 3. Since contaminant levels were extremely high in pit 3 we established two additional test pits on We found diesel with a the Serve-Um-Self property located across Elm Street. concentration of 8.0 ppm in pit 4. Due to the absence of gasoline in this pit, it is unlikely that it is associated with contamination found in pit 3. These sample locations are shown on the Field Form and the analysis results are shown in Appendix B. As required by the DOE, we have completed the Underground Storage Tank Site Check/Site Assessment Checklist and submitted it to the Olympia office. A copy of this checklist is presented in this report as Appendix D.

#### 4.0 Investigative Methods and Results

#### 4.1 Field Screening

For field analysis of compounds containing volatile organics, we use a Foxboro Organic Vapor Analyzer in conjunction with the interim headspace method as recommended by the manufacturer. This method is used to confirm the presence or absence of volatile components in the soil and provides only a rough indication of the contaminant concentrations. The analysis procedure involves:

- 1. Selecting a clean, wide mouth jar (1 qt.) and filling the bottom 1/3 with a discrete soil sample.
- 2. Place aluminum foil over the top of the jar and place a ring over the jar to create a seal.
- 3. Boil the sample for 10 minutes. This causes the volatile compounds to become vapors and collect in the space above the soil.
- 4. Remove the sample from the boiling water and insert the instrument probe through the aluminum foil for vapor analysis.
- 5. Record the instrument response on the FF.

#### 4.2 Soil Sampling

The FF presents the location, quantity and types of samples taken. In general, sample collection and control followed the following protocol:

- 1. Select a laboratory certified clean sample jar for sample collection.
- 2. Using clean latex gloves and clean sampling utensils (tri-sodium phosphate, chlorine solution, tap water rinse and distilled water rinse cycle) tightly pack the soil sample in the sample jar (4 oz.) to the top of the jar to prevent any airspace.
- 3. Label the jar with the soil sample number, the type of laboratory test required, the date, name of site and sampler. The sample is then entered on the chain of custody form.

- 4. Cool the sample in wet ice to approximately 40 C.
- 5. Repack the samples for shipment to the laboratory in blue ice and a cooler.
- 6. Relinquish sample to courier for shipment to the laboratory.

#### 4.3 Soil Chemistry

To determine if soil cleanup is required, we compare laboratory analysis results to Action Levels for Petroleum Releases (Action Levels). These levels (Appendix C) are established in <u>Guidelines for Site Checks and Site Assessments for Underground Storage</u> Tanks.

Based on our comparison, we find that cleanup of Petroleum Contaminated Soil (PCS) is necessary in the area of pit 1 and pit 3 shown on the Field Form (Appendix A).

#### <u>Pit 1</u>

The soil sample collected in pit 1, at a depth of 8 feet, indicates the presence of:

gasoline at a concentration of 95 parts per million (ppm), benzene at a concentration of 7 parts per billion (ppb), toluene at a concentration of 1,550 ppb (1.55 ppm), ethylbenzene at a concentration of 1,690 ppb (1.69 ppm), xylenes at a concentration of 28,400 ppb (28.4 ppm).

Comparison of analysis results with Action Levels for Petroleum Releases (Appendix C) indicates that cleanup of Petroleum Contaminated Soil is required due to the concentration of xylene in the soil. Also, the concentration of gasoline is very near the Action Level. It is likely that concentrations of gasoline exceed Action Levels nearer to the tanks.

#### Pit 2

The soil sample collected in pit 2, at a depth of 7 feet, found no detectable petroleum products. No cleanup action is required at this location.

#### Pit 3

The soil sample collected in pit 3, at a depth of 7 feet, indicates the presence of:

gasoline at a concentration of 180.0 ppm, benzene at a concentration of 5.0 ppb (0.005 ppm), toluene at a concentration of 9,160 ppb (9.16 ppm), ethylbenzene at a concentration of 1,280 ppb (1.28 ppm) and xylenes at a concentration of 35,500 ppb (35.5 ppm).

Comparison of analysis results with Action Levels for Petroleum Releases (Appendix C) indicates that cleanup of Petroleum Contaminated Soil is required due to the concentration of gasoline and xylenes in the soil.

#### Pit 4 & 5

No soil samples were collected from pit 4 or pit 5 due to budget constraints. These pits were established to allow sampling of the groundwater. Analysis of these samples are discussed in section 4.5, <u>Groundwater Chemistry</u>.

Results of soil sample analyses are shown in Appendix B. Comparison of the analyses results with the action levels for cleanup (Appendix C) indicates that cleanup action is required in the area of pit 1 and pit 3.

#### 4.4 Groundwater Sampling

Water sampling followed the same general protocol as the soil samples. However, food grade Mason jars were used to collect the sample. The primary difference lies in filling the sample bottle. We filled the water bottle, placed the cap on the sample and inverted the sample to confirm the absence of air space.

#### 4.5 Groundwater Chemistry

To determine if groundwater cleanup is required, we again compare laboratory analysis results to Action Levels for Petroleum Releases (Action Levels). These levels (Appendix C) are established in <u>Guidelines for Site Checks and Site Assessments for Underground Storage Tanks.</u>

Based on our comparison, we find that cleanup of Petroleum Contaminated Groundwater (PCG) is necessary in the area of pit 3 and pit 4, the locations of which are shown on the Field Form (Appendix A).

#### Pit 1

Laboratory analysis of the groundwater sample collected from pit 1 indicates the presence of:

gasoline at a concentration of 0.05 ppm, toluene at a concentration of 2.0 ppb (0.002 ppm), ethylbenzene at a concentration of 1.0 ppb (0.001 ppm) Xylenes at a concentration of 9 ppb (0.009 ppm).

Benzene was not detected in the analysis. Comparison of analysis results with the Action Levels indicate that cleanup is not required at this location. However, petroleum is present and its appearance in the sample may indicate groundwater and/or soil contamination upgradient from this location.

#### Pit 2

Laboratory analysis of the groundwater sample collected in pit 2 found no detectable petroleum contamination.

#### Pit 3

The groundwater sample collected in pit 3 indicates high concentrations of gasoline. At the dilution required to process the sample, gasoline was the only matrix identified. It is likely that high concentrations of benzene, toluene, ethylbenzene and xylenes are also present. Cleanup of petroleum contaminated groundwater at this location is necessary.

#### Pit 4

The groundwater sample collected in pit 4 indicates the presence of diesel at a concentration of 8.2 ppm. It also contained lead at a concentration of 0.016 ppb. This sample exceeds Action Levels for diesel. However, if this were associated with the contamination found in pit 3, the presence of gasoline or its components would be expected as it is much more mobile than diesel. It is likely that this is not associated with contamination found in pit 3.

#### Pit 5

Analysis of the groundwater sample collected in pit 5 found no detectable petroleum contaminants. No cleanup action is required at this location.

Results of the analyses are shown in Appendix B. Comparison of the analyses results with the <u>Guidance for Site Checks and Site Assessments for Underground Storage Tanks</u> indicates that groundwater cleanup is required in pit 3 and pit 4.

#### 5.0 Recommendations

We understand that the underground storage tanks are not currently in use and are not intended for use in the future. We recommend removing the tanks and proceeding with cleanup of the contaminated media.

During the tank removal process, we suggest monitoring excavated soil with an organic vapor analyzer. This will allow separation of contaminated soil from non-contaminated soil during excavation. The contaminated soil should continue to be removed until laboratory analyses indicate that the remaining soil is "clean". Contaminated soil shall stockpiled upon, and covered with a plastic liner to conform with WSDOE requirements.

The most cost effective method of treatment for petroleum contaminated soil (PCS) consists of on-site or off-site land management (landfarming). The WSDOE has specific requirements for this method of treatment. These consist of:

depth to groundwater must be greater than ten feet, the surface should be level and protected from surface water and runoff, soil containing gasoline shall be spread to a maximum thickness of 6 inches, soil containing diesel shall be spread to a maximum thickness of 3 inches, the treatment area shall be restricted from public access and treatment shall be monitored to ensure treatment progress.

If an adequate treatment site is unavailable, a county landfill will treat the soil if space is available.

Upon excavation of the tanks and removal of contaminated soil, contaminated groundwater should be pumped from the floor of the excavation to remove as much contaminated groundwater as possible. It may be possible to utilize previously excavated tanks for storage of contaminated water if they are in good condition. Removal of contaminated groundwater from the excavation will reduce contaminant concentrations remaining and will reduce in-place treatment and associated costs. The removed contaminated groundwater must be treated through use of air-stripping and/or activated carbon once all free product is removed through gravity separation. If contaminated groundwater remains in-place after pumping an extraction well should be placed within the plume and contaminated groundwater must be pumped and treated by air-stripping and activated carbon until concentrations fall below Action Levels.

Upon removal of contaminated media, and before extraction cleanup is initiated, at least three groundwater monitoring wells should be installed to monitor contaminant concentrations and ensure that contaminants do not migrate from the site.

#### 6.0 Conclusion

Our investigation reveals that cleanup of petroleum contaminated soil is necessary in the area of pit 1. We also find that cleanup of petroleum contaminated groundwater and soil is necessary in the area of pit 3. It is likely that much of the cleanup can be accomplished during and after removal of the tanks. If it is impossible to remove all contamination through excavation and pumping of the excavated area, installation of a pump and treat system is warranted. A cost estimate for treatment is provided separately.

#### 7.0 Limitations

In performing our professional services, we used a degree of care ordinarily exercised under similar circumstances by members of our profession. No warranty, expressed or implied, is made or intended. Our conclusions and recommendations, developed from our field and laboratory investigation reported herein, are based upon this firm's understanding of this particular project and are in concurrence with generally accepted practice.

WHITE SHIELD, INC. P.O. BOX 477 GRANDVIEW, WA 98930 (509) 882-1144

# FIELD FORM FOR SITE ASSESSMENT OF UNDERGROUND STORAGE TANKS

Project name: 10ppenish Brand - Y Project number: REP-0191
Location: SW CORNER of Fort Rd & Elm; 1/4 1/4, Sec. T. N., R. E., W.M.  Field Personnel: D.L. G. & R.L.H. Weather: Sunny, Warm Date: 5-22-91  Tank Contents: Size: Condition:  Size: Condition: Size: Condition:  Tank Contents: Size: Condition: Condition: Size: Condition: Condi
Visual containmation
SITE SKETCH  (Show tank locations, lines, dispenser(s) and sample locations  CHEVRON  FORT RO.
whiled, boody.   Pumps PIT2    Pumps Pimps
Samples descriptions are on reverse.
Depth to  groundwater

#### MTC

Analytical/Environmental Services

Materials Testing & Consulting, Inc.

P.O. Box 309 Mount Vernon, WA 98273

(206)424-7560 - FAX (206)424-7550

Client: White Shield Inc.

Attn: Dave Green

P.O. Box 477

Grandview, WA 98930

Date:

5/9/91

Reference:

91-0123

Project:

Brand X

Data Report

	Sample	ug/gm		ng/gm		
Lab Number	Description	TPH	Benzene	Toluene	Ethlybenzene	Xylenes
31-91-00506.0\$	REP-0191-01	95-G	7	1550	1690	28400
31-91-00507.0W	REP-0191-02	0.05-G	<1	2	1	9
31-91-00508.0\$	REP-0191-03	< 0.05	<5	<5	<5	<5
31-91-00509.0W	REP-0191-04	<0.011	<1	<1	<1	<1
31-91-00510.18	REP-0191-05	180-G	5	9160	1280	35500
31-91-00511.0W	REP-0191-06	Gasoline*				
	* At the dilution required to run sample, gasoline was the only matrix identified.	eort wy solor ort				
	Methods: BTEX/TPH SW846 8020/8015mod. G- Gasoline D- Diesel					
		Eo:I/Water	Boll/Water	Boll/₩ater	Boll/Water	Boll/Water
	Method Reporting Limit (MRL)	0.03/0.01	8/1	6/1	5/1	5/1
	Maximum Contamination Levels	100/1	500/6	20000/20	40000/40	20000/20

Kurt W. Larsen Sr. Enviromental Chemist Post-It's brand fax transmittal memo 7671 # of pages > 1

To Do boic From That Larsen

Dept. Phone #

Fax #

Fax #

Fax #

Fax #

#### Appendix B

MTC

Analytical/Environmental Services

Materials Testing & Consulting, Inc

WSDOH Laboratory #46092090

P.O. Box 309

Mount Vernon, WA 98273

(206)424-7560 - FAX (208)424-7550

Client: White Shield Inc.

P.O. Box 477

Grandview, WA 98930

Date:

5/24/91

Reference: 91-0168

Attn: Mr. Dave Green

Project: Toppenish Brand X

### Data Report

	Sample	ug/gm		ng/gm		
Lab Number	Description	TPH	Benzene	Toluene	Ethlybenzene	Xylenes
31-91-00598.0W	REP-0191-07	8.2-D	<1	< 1	<1	<1
31-91-00599. <b>0W</b>	REP-0191-08	< 0.01	<1	< 1	<1	<1
	Methode:					
	BTEX/TPH \$W846 8020/8016	mod.				A - A 10 100 1
	G-Gasoline D-	Diese! Bol/Wa'er	Soll/Waler	Eolt/Walar	Soll/Water	Boll/Waler
	Method Reporting Limit (MRL)	0.05/0.01	6/1	5/1	8/1	6/1
	Maximum Contamination Leve	als 100/1	500,6	20000/20	40000/40	20000/20

Sr. Environmental Chemist

#### Appendix B

M	8	11/1	~
TVI		п	
X V JI	9.	E A	-

Analytical/Environmental Services

Materials Testing & Consulting, Inc.

P.O. Box 309

Mount Vernon, WA 98273

(206)424-7560 - FAX (206)424-7550

Client: White Shield Inc.

P.O. Box 477

Grandvlew, WA 98930

Date:

5/24/91

Reference:

91-0168

Attn: Mr. Dave Green

Project: Toppenish Brand X

#### Data Report

Lab Number 31-91-00598.0W	Sample Description	mg/gm Pb	
31-91-00598.0W	PED 0101.07	CHARLE & SPINISHES AND ASSESSMENT OF THE PROPERTY OF THE PARTY OF THE	
	WEL AIRLAN	0.016	
	Methods; \$W846 3050/7421		
	Method Reporting Limit (MRL)	0.005	

(Kusth Vaisen) L.J. Henderson, Phi

Lab Director

WHITE SHIELD INC.     P. O. BOX 477    GRANDVIEW, WA. 98930    (509) 882-1144    (509) 882-4588 FAX		CHAIN	OF CUST	YODY		IPROJECT I IPROJECT I IDESTINATI ISAMPLER IDATE ST	1 R. 1 101 W	CP-C 1.T.C	219) GR 8	FEN	490'7	enns	H	
SAMPLE MUMBER	200	AMALYS	IS REQUI	STED /	/ /	/ ./	/ /	/ /	/ //	/ /	/ !	/ !	/ !	  -    - 
REP-0191-7	-	X	Χ	******			 	 		2000	}     annuar		 	1 1
REP-0191-8	<u>K</u>	Χ.	.۲.				     	 	 		   			;
^~~~~			*****		     		51	7	R	DE		ΓY		
**************************************	enenan enenan	******	******		   	Ple	950	4	k y lat	esm	1+5 1	5-2	4-91	
						.    	     	     	 				 	
		 		   	!   		¹   	! !	   	! ! !	   	i   	] 	
IRELINOVIBLED BY MEN!				ils		IRELANQUI	Avergo		· )	\ !	4,	SHED BY	***	'aaa'       
RECELVED BY (SIGN)	1 / 00			i	I RECEIVED BY (SIGN) / 800 13. I SIGN / 800 1 SIGN / 800			, 	IRECEIVED BY (SIGH) 14. 1DAYE TIME			!		
I NETHOD OF SHIPHEHT			<u>.</u> /.	6246m#P4		I RECEIVED	FOR LAB	CORATORY	(KB18)	3044404   	DATE	1H1		-
***********	 		••								3534655			

#### Appendix C

#### Action Levels for Petroleum Releases

Indicator Constituent	CAS <u>Number</u> <sup>1</sup>	Groundwater Action <u>Level</u>	Soil Action <u>Level</u>
Benzene	71-43-2	1 µg/L <sup>2,4</sup>	0.5 mg/kg
Ethylbenzene	100-41-4	30 µg/L	20 mg/kg
Toluene	108-88-3	40 µg/L	40 mg/kg
Xylene	1330-20-7	20 μg/L	20 mg/kg
TPH (gasoline)		1,000 µg/L	100 mg/kg
TPH (other than gasoline)		1,000 µg/L	200 mg/kg
Lead	7439-92-1	5.0 µg/L	250 mg/kg

CAS number is the Chemical Abstracting Service number; "---" means no CAS number has been defined for these constituents.

<sup>2</sup> 

<sup>3</sup> 

μg/L can also be expressed as ppb.
mg/kg can also be expressed as ppm.
Groundwater quality based criteria (Chapter 173-200 WAC).



Depth to groundwater \_ (3

Approximate scale: Not to Scale

# FIELD FORM FOR SITE ASSESSMENT OF UNDERGROUND STORAGE TANKS

Date: 5-22 - 9

Project name: Toppenish Brand - Y Project number: REP-0191 of Fort Rd & Elm. Location: SW CORNER \_1/4 \_\_\_\_1/4, Sec.\_\_\_, T.\_\_\_N., R.\_\_\_ E., W.M. Field Personnel: D.L. G. & RLH. Weather: Sunny, Warm Date: 5-22-91 \_\_ Condition: Tank Contents: . Size: \_\_ Condition:\_ Size: Tank Contents: \_ Size:\_ \_\_\_\_\_ Condition: Tank Contents: . Size:\_ \_\_\_\_\_ Condition: Tank Contents: Size:\_ \_\_\_\_ Condition: \_ Tank Contents: \_ \_Odors:\_ Ambient vapors:\_ \_ Vapors in excavation:\_ Basaltic Flood silt to NG River Graves Soil texture and structures:\_ 2 heavy confamination above quater in PIT3 Screening method: Visual contamination: 7-11 SITE SKETCH (Show tank locations, lines, dispenser(s) and sample locations CHEVROM North Direction RD. FORT unlead, 6000 yel Pumps PRIMPS PUMPS Reg, 6000 gal. SERV PUMPS SELF GRAVELED AREA BRAND STORE 4,000gal pit Ś CAR WASH 00000 SUPER UNLEAD 40004 Gas line madrine Property Gasoline Emknown diesel) size Ground water Flow Samples descriptions are on reverse. I certify that the work performed and sampling methods used meet regulatory requirements as set forth by the U.S. Environmental Protection Agency and the Washington State Department of Ecology.

Site Assessor:

#### REQUIRED SAMPLES

Display locations on site sketch

Dispenser 1 (two feet below pipe).	O
Analysis: Depth:	Analysis:Depth:
Headspace readingppm.	Headspace readingppm.
If there is more than one dispenser, include corresponding	O
samples under Additional Sampling	Analysis: Depth:
	Headspace readingppm.
Fuel lines (first 50 feet of length).	O
Analysis: Depth:	Analysis: Depth:
Headspace readingppm.	Headspace reading ppm.
If there is more than 50 ' of lines, include corresponding samples under Additional Sampling	0
= 2	
ADDITIONAL SAMPLING	Analysis: Depth:
ADDITIONAL SAME	Headspace readingppm.
1 PIT 1 - Soil	0
Analysis:Depth:	Analysis: Depth:
Headspace reading Z.Z ppm.	Headspace readingppm.
a = = = = = = = = = = = = = = = = = = =	0
(2) Depth:	Analysis: Depth:
	Headspace readingppm.
Headspace reading No deled ppm.	O
3 PIT Z - Soil	Analysis: Depth:
Analysis: Depth:	Headspace readingppm.
Headspace reading 1.0 ppm.	
(A) PITZ - Water	
Analysis: Depth: 13	Analysis: Depth:
Headspace reading 0.4 ppm.	Headspace readingppm.
	O
(5) PIT 3 - 501	Analysis: Depth:
Analysis: Depth:  Headspace reading no detect ppm.	Headspace readingppm.
	O
6 PIT 3 - water	Analysis: Depth:
Analysis: Depth: 13'	Headspace readingppm.
Headspace reading $\frac{71000, 0}{ppm}$	O
7 Pit 4 - worker	0
Analysis: Depth: 13	Analysis: Depth:
Headspace reading 45.0 ppm.	Headspace readingppm.
~ = = =d.=	O ————
8 PIT 5 - water	Analysis: Depth:
Analysis: Depth:	Headspace readingppm.
Headspace reading No Doled ppm.	the state of the s